

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403777513

Date Received:

05/02/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

4 of 6 CAs from the FIR responded to on this Form

4 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Luke Kelly

Phone

970-939-6353

Email

lkelly@civiresources.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 713900527

Inspection Date: 04/04/2024

FIR Submit Date: 04/15/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: HIGHPOINT OPERATING CORPORATION

Company Number: 10071

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 444840

Location Name: Anschutz Equus Farms Number: 4-62-28 NWNW County: \_\_\_\_\_

Qtrqtr: NWN Sec: 28 Twp: 4N Range: 62W Meridian: 6

Latitude: 40.287881 Longitude: -104.337456

### FACILITY - API Number: 05-123- -00 Facility ID: 444840

Facility Name: Anschutz Equus Farms Number: 4-62-28 NWNW

Qtrqtr: NWN Sec: 28 Twp: 4N Range: 62W Meridian: 6

Latitude: 40.287881 Longitude: -104.337456

### CORRECTIVE ACTIONS:

1 CA# 194384

Corrective Action: Remove stained soil per Rule 912.a.

Date: 05/15/2024

Response: CA COMPLETED

Date of Completion: 04/30/2024

Operator Comment: Operator has reported the stained soil has been addressed and disposed of appropriately to comply with Rule 912.a.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 194385

Corrective Action: Comply with Rule 606.

Date: 04/22/2024

Response: CA COMPLETED

Date of Completion: 04/30/2024

Operator  
Comment: Operator has reported that identified trash receptacle has been closed and signage added to remind the Field. Debris/trash on location has been cleared to comply with Rule 606.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**3** CA# 194386

Corrective Action: Install wildlife protection equipment correctly per Rule 608.

Date: 04/22/2024

Response: CA COMPLETED

Date of Completion: 04/30/2024

Operator  
Comment: Operator has appropriately installed wildlife netting to comply with Rule 608.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**4** CA# 194387

Corrective Action: Comply with Rule 606.

Date: 04/30/2024

Response: CA COMPLETED

Date of Completion: 04/30/2024

Operator  
Comment: Operator has reported that identified pallet and wattles on location have been successfully removed to comply with Rule 606.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Ashley Noonan

Signed: \_\_\_\_\_

Title: Sr Regulatory Analyst

Date: 5/2/2024 2:44:01 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403777528	Inspection Resolution Report

Total Attach: 1 Files