

Operator: HIGHPOINT OPERATING CORPORATION
Location Name: Anschutz Equus Farms 4-62-28 NWNW
Loc ID: 444840
Inspection: 713900527



Exhibit A

CA: Stained soil observed on the location and unplugged hoses throughout the production pad. Remove stained soil per Rule 912.a.

CA Resolution: Operator has reported the stained soil has been addressed and disposed of appropriately to comply with Rule 912.a.



Exhibit A

CA: Trash receptacle is being left open and allowing trash to blow and distribute across the production facility. Comply with Rule 606.

CA Resolution: Operator has reported that identified trash receptacle has been closed and signage added to remind the Field. Debris/trash on location has been cleared to comply with Rule 606.



Exhibit A

CA: Wildlife netting was incorrectly installed and should cover the entire secondary containment. Install wildlife protection equipment correctly per Rule 608.

CA Resolution: Operator has appropriately installed wildlife netting to comply with Rule 608.



Exhibit A

CA: A pallet of wattle was observed being stored on the production pad. Comply with Rule 606.

CA Resolution: Operator has reported that identified pallet and wattles on location have been successfully removed to comply with Rule 606.