

Inspection Photos

API: 017-07127

Operator: CITATION OIL & GAS CORP

Inspection Date: 5/1/2024

County: CHEYENNE



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west at the beginning of the access road. The cattleguard has not been removed..



Inspection Photos



Photo 2. Facing east along the former access road. There is a definitive area along the former road that is not establishing crop growth. Consider checking for compaction issues.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-07127 | Date: 5/1/2024

Inspection Photos




Photo 3. Facing west toward the abandoned wellsite location. There are pipe risers and lines that have not been abandoned and removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-07127 | Date: 5/1/2024

Inspection Photos



Photo 4. Facing down toward the abandoned wellsite. There are pipe risers and lines that have not been abandoned and removed and are interfering with crop production.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 5. Facing east down toward the abandoned wellsite. It appears there is no crop growth coming up to the left of the pipe risers.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:017-07127 | Date: 5/1/2024