

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: PRONGHORN-65N61W 16NENE

Loc ID: 305298

Inspection: 708201162



Ex

Exhibit A



Exhibit B



Exhibit C



Exhibit D

CA: This location does not comply with Rule 1004. Reclamation rules require reclamation activities to be conducted within twelve (12) months on non-cropland. Well was plugged 01/06/2014. During this inspection, it was observed that the former access road, well and tank battery are predominantly bare/exposed soils, which are un-stabilized in their current state. Additional reclamation activities are required. Refer to attached inspection photos. Comply with Rule 1004. Reseed disturbance areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial,

non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

CA Resolution: Operator has reported and provided photo evidence of actions taken to comply with ECMC Rule 1004. The location has now been appropriately mowed to assist with mitigating undesirable vegetation, and re-seeded/straw crimped to encourage new growth and soil stabilization.