

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403776573

Date Received:

05/02/2024

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1099 18TH STREET SUITE 1500

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

rbucogccinspectionreports@chevron.onmicrosoft.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708200782

Inspection Date: 12/28/2023

FIR Submit Date: 01/02/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: NOBLE ENERGY INC

Company Number: 100322

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 425346

Location Name: McClellan PC

Number: LG03-78HN

County: \_\_\_\_\_

Qtrqtr: SWS Sec: 3 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.684740 Longitude: -103.969330

### FACILITY - API Number: 05-123-

-00

Facility ID: 425346

Facility Name: McClellan PC

Number: LG03-78HN

Qtrqtr: SWS Sec: 3 Twp: 8N Range: 59W Meridian: 6

Latitude: 40.684740 Longitude: -103.969330

### CORRECTIVE ACTIONS:

1 CA# 189744

Corrective Action: Comply with Rule 606 and remove any unused equipment. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/28/2023

Response: CA COMPLETED

Date of Completion: 01/09/2024

Operator Comment: Complied with rule 606. FIRR by Javier Doc# 403655212

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 189745

Corrective Action: Install sign to comply with Rule 605.g. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/28/2023

Response: CA COMPLETED

Date of Completion: 05/09/2024

Operator  
Comment: complied with rule 606.g.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**3** CA# 189746

Corrective Action: Properly dispose of oily waste in accordance with Rule 905.e. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/28/2023

Response: CA COMPLETED

Date of Completion: 01/09/2024

Operator  
Comment: complied with rule 905.e. FIRR by Javier Doc # 403655212

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**4** CA# 189747

Corrective Action: Install sign to comply with Rule 605.g. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/28/2023

Response: CA COMPLETED

Date of Completion: 01/09/2024

Operator  
Comment: complied rule 605.g. FIRR by Javier Doc # 403655212

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**5** CA# 189748

Corrective Action: Comply with Rule 1003. The location will remain out of compliance until the corrective action has been resolved.

Date: 12/28/2023

Response: CA COMPLETED

Date of Completion: 04/30/2024

Operator  
Comment: Complied with Rule 1003.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Finished last Corrective Action and complied with Rule 1003.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff White

Signed: \_\_\_\_\_

Title: HSE

Date: 5/2/2024 7:36:20 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

403776573	FIR RESOLUTION SUBMITTED
403776596	photo

Total Attach: 2 Files