

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403149198

Date Received:

08/29/2022

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

3 of 5 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 700300437

Inspection Date: 08/18/2022

FIR Submit Date: 08/19/2022

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

### LOCATION - Location ID: 312083

Location Name: TIFFANY Number: 5 County: \_\_\_\_\_

Qtrqtr: SWSE Sec: 20 Twp: 33N Range: 6W Meridian: N

Latitude: 37.085058 Longitude: -107.519749

### FACILITY - API Number: 05-067- -00 Facility ID: 312083

Facility Name: TIFFANY Number: 5

Qtrqtr: SWSE Sec: 20 Twp: 33N Range: 6W Meridian: N

Latitude: 37.085058 Longitude: -107.519749

### CORRECTIVE ACTIONS:

1 CA# 163973

Corrective Action: remove trash or store in appropriate recepticals

Date: 08/26/2022

Response: CA COMPLETED

Date of Completion: 08/25/2022

Operator Comment: Trash has been removed. See the attached photos. Per the landowner signed agreement, wood from the pad build is piled next to the pad for landowner use.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 163974

Corrective Action: remove unused equipment not needed for ongoing operations

Date: 09/19/2022

Response: CA COMPLETED

Date of Completion: 08/25/2022

Operator Comment: The Hott 20-2 1 well (067-06629) plug and abandonment downhole actions are not complete and the associated Form 6, which finalizes the P&A status and starts the timeline for the flowline and equipment stripping, is not approved. IKAV Energy/SIMCOE is in active conversations with COGCC Engineering Staff, A. Duran, regarding the status of the well. The anticipated timeline for approval of the Form 6 is after September 30, 2022. Loose, scattered, unused parts and supplies have been removed as of 08/25/2022. See attached photos.

ECMC Decision:

ECMC  
Representative:

3 CA# 163975

Corrective Action: remove debris or employ BMPs to prevent potential wildlife entanglement

Date: 08/26/2022

Response: CA COMPLETED

Date of Completion: 08/25/2022

Operator Comment: Debris has been removed. See attached photos.

ECMC Decision:

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA's marked complete for items addressed. Remaining items continue to be worked.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Katherine Feir

Signed:

Title: Compliance Coordinator

Date: 8/29/2022 8:28:38 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403149198	FIR RESOLUTION SUBMITTED
403149219	Trash, loose unused equipment, debris removal completion photos

Total Attach: 2 Files