

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403265694

Date Received:
12/20/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 95960

Name of Operator: WEXPRO COMPANY

Address: P O BOX 45003

City: SALT LAKE CITY State: UT Zip: 84145-0601

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Tammy Fredrickson	3073527514	Tammy.Fredrickson@dominionenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 689801864

Inspection Date: 10/30/2018

FIR Submit Date: 10/31/2018

FIR Status: _____

Inspected Operator Information:

Company Name: QEP ENERGY COMPANY

Company Number: 10343

Address: 1050 17TH STREET - SUITE 800

City: DENVER State: CO Zip: 80265

LOCATION - Location ID: 313408

Location Name: SPARKS RIDGE UNIT-611N101W Number: 7NENW County: MOFFAT

Qtrqr: NENW Sec: 7 Twp: 11N Range: 101W Meridian: 6

Latitude: 40.933171 Longitude: -108.794155

FACILITY - API Number: 05-081-00 Facility ID: 298146

Facility Name: SPARKS RIDGE UNIT Number: 2 H

Qtrqr: NENW Sec: 7 Twp: 11N Range: 101W Meridian: 6

Latitude: 40.933171 Longitude: -108.794155

CORRECTIVE ACTIONS:

1 CA# 120053

Corrective Action: Install sign to comply with Rule 210.b.

Date: 12/31/2018

Response: CA COMPLETED

Date of Completion: 11/15/2021

Operator Comment: The location sign has been modified to show the county road. Completed by HRM Resources.

ECMC Decision: _____

ECMC
Representative:

2 CA# 120054

Corrective Action: Install sign to comply with Rule 210.b.

Date: 12/31/2018

Response: CA COMPLETED

Date of Completion: 11/15/2021

Operator
Comment:

A wellhead sign has been attached to the wellhead. Completed by HRM Resources.

ECMC Decision:

ECMC
Representative:

3 CA# 120055

Corrective Action: Properly treat or dispose of oily waste in accordance with 907.e.
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition,
inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 11/30/2018

Response: CA COMPLETED

Date of Completion: 11/15/2021

Operator
Comment:

Stained soil has been removed, the wellhead has been wiped down, oil gator (absorber) has been spread around the wellhead and fresh dirt applied to the area. All pipes, valves and fittings have been attached and inspected and are in good working order.

ECMC Decision:

ECMC
Representative:

4 CA# 120056

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.

Date: 11/12/2018

Response: CA COMPLETED

Date of Completion: 11/15/2021

Operator
Comment:

MIT was completed in 2018 and submitted by HRM in 2021 under document # 402868150.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Submitted by new operator, pending Form 9 transfer approval. Researched and found items to have been completed but not all had been submitted in a FIRR notice.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Fredrickson

Signed: _____

Title: Senior Permit Agent

Date: 12/20/2022 7:22:01 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403265694	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files