

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402814265

Date Received:

09/16/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

Adamczyk, Megan

megan.adamczyk@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 700300270

Inspection Date: 09/10/2021

FIR Submit Date: 09/14/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306783

Location Name: COLE, JAMES GAS UNIT B- N34N8W Number: 8SWSW County: LA PLATA

Qtrqr: SWS Sec: 8 Twp: 34N Range: 8W Meridian: N
W

Latitude: 37.225700 Longitude: -107.773836

FACILITY - API Number: 05-067-00 Facility ID: 264756

Facility Name: JAMES COLE B Number: 2

Qtrqr: SWS Sec: 8 Twp: 34N Range: 8W Meridian: N
W

Latitude: 37.225700 Longitude: -107.773836

CORRECTIVE ACTIONS:

2 CA# 155775

Corrective Action: Repair or replace deteriorated sound panel/sound mitigation materials (see photo), use engineered materials and maintain with best engineering practices with an emphasis to low frequency (c-scale) noise.

Date: 09/21/2021

Response: CA COMPLETED

Date of Completion: 09/15/2021

replaced and/or repaired insulation in panel. see photo attached.

--

Comment:	CA completed
----------	--------------

Print Name: Karin Rhodes Signed: _____
Title: admin asst Date: 9/16/2021 1:37:20 PM

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402814265	FIR RESOLUTION SUBMITTED
402814267	picture of sound panel work completed

Date Run: 5/4/2024 Doc [#402814265]