

# Inspection Photos

May 2nd, 2024

Operator: Merrion Oil and Gas Corp - 56680

Location ID: 333388

Inspection Document #: 714000734

La Plata County, CO

Township: NWSE 15 33N 7W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: B E Behrmann 1  
Location ID: 333388

5/2/24  
+37.100977,-107.592574  
33° NE



Photo 1. View of the well disturbance from the access point facing center.


Inspection Photos  
Location Name: B E Behrmann 1  
Location ID: 333388

5/2/24  
+37.100858,-107.592549  
180° S



**Photo 2.** Produced water tank label and weeds at berm corrective actions identified in the previous inspection doc #702500045 have been addressed/resolved.

Inspection Photos  
Location Name: B E Behrmann 1  
Location ID: 333388



Inspection Photos  
Location Name: B E Behrmann 1  
Location ID: 333388



**Photo 4.** View of the eastern interim reclamation area facing southeast. Vegetation comprised of crested, western wheatgrass and rabbit brush.

Inspection Photos  
Location Name: B E Behrmann 1  
Location ID: 333388



**Photo 5.** Reference area comprised of crested wheatgrass, sage brush and juniper.

