

## WELL SITE INSPECTION FORM



WELL NAME Denny #1  
OPERATOR H+R Well Service  
LOCATION NWSE 27-7N-67W  
FIELD New Windsor

API NUMBER 05 - -  
PERMIT NUMBER   
COUNTY Well  
INSPECTOR SP

## AL/PA/DA INSPECTION RESULTS:

PASS(Y)  FAIL(N)  DATE  FN  FD  WO

=====

DATE OF INSPECTION BEFORE/DURING DRILLING

CASING SIZE  DEPTH SET  CMT VOL  WOC   
CONSISTENT WITH APD CASING PROGRAM?  RETURNS   
RIG  BOP'S  CONTACT

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION

PIPE SET?  COMPLETION RIG/ACTIVITY   
DRILLING PITS: CLOSED  OPEN  WELLHEAD SYSTEM INSTALLED   
TANK ID: YES  NO  NA  WELL SIGN: YES  NO   
SKIM PIT: gal TANKS: (  )  bbls  
EQUIPMENT

BRADENHEAD PRESSURE  FLUID: NO  YES  TYPE   
METER RUN: YES  NO  WELL STATUS: PR  TA  SI  WELL CAT 3-

## AL/PA/DA INSPECTION

DATE PLUGGED:  DATE PERMIT EXPIRED:   
HOLE PLUGGED: YES  NO  PITS BACKFILLED: YES  NO   
MATERIAL BURIED: YES  NO  NA  SITE CLEAN: YES  NO   
BOND RELEASE OK: YES  NO  FED  HOLE MARKER: YES  NO

DATE OF SAFETY/STATUS INSPECTION 8/22/89

COMMENTS Plug back to Parkman - well presently T.A.  
4 1/2" pipe - welded to 1" rubber hose running  
to oil water truck. Tank is full of water  
w/ slight paraffin slum on top.

Wtr Truck = Stanco