

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Speakman/A Pad

Location ID: 422301

Date: 5/7/2024



Location Entrance – Photo #00985



Wellheads – Photo #00990

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Speakman/A Pad

Location ID: 422301

Date: 5/7/2024



May 7, 2024 at 13:33:18
5242 County Road 300
Parachute CO 81635
United States



May 7, 2024 at 13:31:12
5242 County Road 300
Parachute CO 81635
United States

Wellheads – Photo #00991

Separators/ECD – Photo #00989

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Speakman/A Pad

Location ID: 422301

Date: 5/7/2024



May 7, 2024 at 13:29:21
5242 County Road 300
Parachute CO 81635
United States



May 7, 2024 at 13:34:27
5242 County Road 300
Parachute CO 81635
United States

Tank Battery – Photo #00986


Tank Battery – Photo #00992

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Speakman/A Pad

Location ID: 422301

Date: 5/7/2024



ECD/Line Heater – Photo #00988



Lack of Stabilization – Photo #00994

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Speakman/A Pad

Location ID: 422301

Date: 5/7/2024



Lack of Stabilization – Photo #00995



Lack of Stabilization – Photo #00998

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Speakman/A Pad

Location ID: 422301

Date: 5/7/2024



Debris – Photo #00999



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #01000

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Speakman/A Pad

Location ID: 422301

Date: 5/7/2024



Insufficient Tracking BMP – Photo #00997