

Inspection Photos on 5/7/24
Operator: Phoenix Resources
Location Name: Holt 1
API: 05-009-06676



Tank battery and treater



Fencing debris on east side of unit

Inspection #715200205

Inspection Photos on 5/7/24
Operator: Phoenix Resources
Location Name: Holt 1
API: 05-009-06676



Inspection #715200205

**Wellhead photo of valves
and current well status**



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources