

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403788745

Date Received:
05/13/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714000704

Inspection Date: 04/23/2024

FIR Submit Date: 04/24/2024

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 320858

Location Name: CARMELITA GALLEGOS A Number: 1 County: ARCHULETA

Qtrqtr: SWSE Sec: 17 Twp: 32N Range: 5W Meridian: N

Latitude: 37.013092 Longitude: -107.411823

FACILITY - API Number: 05-007-00 Facility ID: 449467

Facility Name: Carmelita Gallegos A Number: 3

Qtrqtr: SWSE Sec: 17 Twp: 32N Range: 5W Meridian: N

Latitude: 37.013092 Longitude: -107.411823

CORRECTIVE ACTIONS:

1 CA# 194673

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 906 and 1002.

Date: 04/29/2024

Response: CA COMPLETED

Date of Completion: 05/05/2024

Operator Comment: Stained material clean up and removed.

ECMC Decision: _____

Date: 5/13/2024 3:28:47 PM

Page 2 of 2