

Inspection Photos
Location: Dawson A 1
Facility ID: 324797



Photo 1 –Well Placard



Photo 2 – Pump Jack

Inspection Photos
Location: Dawson A 1
Facility ID: 324797



Photo 3 – Pump Jack

Photo 4 – Tank Battery

Inspection Photos
Location: Dawson A 1
Facility ID: 324797



Photo 5 – Tank Battery / Treater

Photo 6 – Tank Battery / Treater

Inspection Photos
Location: Dawson A 1
Facility ID: 324797



Photo 7 – Remediation Excavation, Remediation # 20712

Photo 8 – Impacted soils in Remediation Excavation

Inspection Photos
Location: Dawson A 1
Facility ID: 324797



Photo 9 – Impacted soils in Remediation Excavation

Photo 10 – Remediation Excavation