

Inspection Photos
Location Name: MEYER B-65N64W/2SESE
Location #: 323739



Photo #1

Meyer B 2-16 (123-13450) Wellsite
Plugged & Abandoned | PA
Cut / Capped
~ 30 yds.



Photo #2

Meyer B 2-16, M & M B 2-23 Battery site
Abandoned: ALL Equipment Removed
Plugged & Abandoned | PA
2: wells

