

Inspection Photos  
Location Name: Nessu 1,2,3,4,12,14,16 battery  
Location ID: 317790



Photo 1 Well site.



Photo 2 WH sign.

Inspection Photos  
Location Name: Nessu 1  
Location ID: 336288



Photo 3 Tank battery site.

Photo 4 Trash on the TB fencing.

Inspection Photos  
Location Name: Nessu 1  
Location ID: 336288



Photo 5 Tank battery sign, Fencing covered with trash.

Photo 6 Trash on the TB fencing.

Inspection Photos  
Location Name: Nessu 1  
Location ID: 336288



Photo 7 Tank battery.



Photo 8 Dumped debris SW of the TB.

**Inspection Photos**  
**Location Name: Nessu 1**  
**Location ID: 336288**



**Photo 9 Dumped debris SW of the TB.**



**Photo 10 Horizontal Heater Treater.**

**Inspection Photos**  
**Location Name: Nessu 1**  
**Location ID: 336288**



**Photo 11 Vegetation around the Heater Treater need to be addressed.**

**Photo 12 Vegetation around the Heater Treater need to be addressed.**

Inspection Photos  
Location Name: Nessu 1  
Location ID: 336288



**Photo 13 Vegetation around the Heater Treater need to be addressed.**