

Argali Exploration Company
Schieck 11-31
Location ID: 312984



Production pit fencing not maintained.



Production pit bordering natural drainage area.

Argali Exploration Company
Schieck 11-31
Location ID: 312984



Open ended tank valve



Damaged equipment. Repair or remove line.

Argali Exploration Company
Schieck 11-31
Location ID: 312984



Open ended load valve



Condensate tank without proper containment next to a natural drainage area

Argali Exploration Company
Schieck 11-31
Location ID: 312984



Inadequate tank berm. Natural drainage behind tank.



Debris

Argali Exploration Company
Schieck 11-31
Location ID: 312984



Riser cap missing



Missing label

Argali Exploration Company
Schieck 11-31
Location ID: 312984



Unused equipment



Debris. Unused equipment.

Argali Exploration Company
Schieck 11-31
Location ID: 312984



Debris



Debris

Argali Exploration Company
Schieck 11-31
Location ID: 312984



Location from Northeast corner



Location from Northwest corner

**Argali Exploration Company
Schieck 11-31
Location ID: 312984**



Location from Southwest corner



Location from Southeast corner