

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7382 From entrance to location



Photo # 7383 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7384 Location



Photo # 7385 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7386 Location



Photo # 7387 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7388 Location



Photo # 7389 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



May 16, 2024 at 12:25:19 PM
CO

Photo # 7390 Location



May 16, 2024 at 12:25:57 PM
CO

Photo # 7391 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7392 Location




Photo # 7393 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7394 Location



Photo # 7395 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7396 Location



Photo # 7397 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7398 Location



Photo # 7399 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7400 Location



Photo # 7401 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7402 Location



Photo # 7403 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030




Photo # 7404 Location



Photo # 7405 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7406 Location



Photo # 7407 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030




Photo # 7408 Location



Photo # 7409 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7410 Location



Photo # 7411 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7412 PRV vent line cap blown off/vent line does not comply with CECMC pressure safety device rules



Photo # 7413 PRV vent line cap blown off/vent line does not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7414 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 7415 VRU tank lacks required labeling

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7416 Open ended piping on VRU tank/wildlife hazard




Photo # 7417 Open ended piping on VRU tank/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7418 Tanks lack required labeling



Photo # 7419 Open ended piping on tank/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7420 Open ended piping on tank/wildlife hazard



Photo # 7421 Location sign lacks required information/does not comply with CECMC rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7422 Diesel tank lacks required labeling



Photo # 7423 Diesel tank lacks required labeling

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7424 Tank lacks required labeling



Photo # 7425 Tank lacks required labeling

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7426 Methanol tank lacks required labeling



Photo # 7427 Methanol tank lacks required labeling



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7428 Tank lacks required labeling



Photo # 7429 Tank lacks required labeling



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7430 Tank lacks required labeling



Photo # 7431 Tank lacks required labeling

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7432 Tank lacks required labeling



Photo # 7433 Tank lacks required labeling

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BAILEY COMPRESSOR STATION

Facility ID: 412030



Photo # 7434 Debris