

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: Latham 14-12 Facility

Loc ID: 429893

Inspection: 713900513



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G



Exhibit H



Exhibit I

CA: Barbed wire fencing remains around the tank battery facility and flowline corridor. It does not appear there is currently any cattle grazing in the area and so fencing should be removed. Remove fencing to comply with Rule 1004.

CA Resolution: Operator has reported that the fence was been removed from the east and north side of the facility location and the north side of the flowline corridor. The fence along the west side of the facility pad was left in place since it ties into the landowner's fence that continues to the north beyond location disturbance area. The fence along the location access road was left in place to prevent wildlife or future grazing of animals from accessing lease roads and pads. Operator also notes that they added a section with a drop gate along the south edge of where the facility was for access. Location currently complies with Rule 1004.