

**Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC**

**Location Name: STATE PRONGHORN-65N61W 16NWNW**

**Loc ID: 306270**

**Inspection: 708201161**



**Exhibit A**



**Exhibit B**



**Exhibit C**



Exhibit D



**Exhibit E**



**Exhibit F**



**Exhibit G**



**Exhibit H**



**Exhibit I**

**CA:** Barbed wire fencing remains around the tank battery facility and flowline corridor. It does not appear there is currently any cattle grazing in the area and so fencing should be removed. Remove fencing to comply with Rule 1004.

**CA Resolution:** Operator has reported that the location has been appropriately mowed to address weeds and undesirable vegetation. Operator has also noted that the location was stripped or remaining road-base, recontoured, re-seeded, and straw crimped to provide stabilization and promote growth. Location currently complies with Rule 1004.