

# Interim Reclamation and Stormwater Inspection

April 15, 2024

Operator: FULCRUM ENERGY OPERATING LLC- #10805

Location ID: 445005

Inspection Document #: 697505281

Jackson County, CO

Chris Binschus  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



**Photo 1.** Drone imagery illustrates Fulcrum's 3rd party cloud computing/data processing company along the western perimeter of the working pad surface.





**Photo 2.** Drone imagery illustrates Fulcrum's 3rd party cloud computing/data processing company along the western and southern perimeter of the working pad surface.



Inspection Photos  
Location Name: Surprise Unit 0680 S9  
Location ID: 445005



**Photo 3.** Photo taken from the entrance of location. Photo illustrates the Location Operator sign.



**Photo 4.** Photo taken from the western working pad surface, facing West. Photo illustrates the equipment and secondary containment has proper wildlife protection.

Inspection Photos  
Location Name: Surprise Unit 0680 S9  
Location ID: 445005



**Photo 5.** Photo taken from the southern working pad surface, facing Southeast. Photo illustrates the equipment and secondary containment lacks wildlife protection.



Inspection Photos  
Location Name: Surprise Unit 0680 S9  
Location ID: 445005




**Photo 6.** Photo taken from the southeastern working pad surface, facing East. Photo illustrates a snow plow pile with random debris. Operator reported that as the pile melts debris is being removed and being properly disposed of.





Inspection Photos  
Location Name: Surprise Unit 0680 S9  
Location ID: 445005



**Photo 7.** ECMC GIS aerial imagery illustrates the location falls within Greater Sage Grouse Priority Habitat Management Area.