

Interim Reclamation and Stormwater Inspection

April 15, 2024

Operator: FULCRUM ENERGY OPERATING LLC- #10805

Location ID: 416625

Inspection Document #: 697505285

Jackson County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Surprise-Damfino S6 Pad
Location ID: 416625



Photo 1. Photo taken from the entrance of location. Photo illustrates the Location Operator sign.



Photo 2. Photo taken from the eastern location, facing North. Photo illustrates the topsoil stockpile which has not been properly stabilized and the perimeter BMP has not been maintained.

Inspection Photos
Location Name: Surprise-Damfino S6 Pad
Location ID: 416625



Photo 3. Photo taken from the eastern location, facing North. Photo illustrates the topsoil stockpile has not been properly stabilized and is eroding due to vertical slopes. The perimeter BMP does not appear to be an appropriate BMP given the snow accumulation in the winter months, which will continue to cause failures.



Inspection Photos
Location Name: Surprise-Damfino S6 Pad
Location ID: 416625



Photo 4. ECMC GIS aerial imagery illustrates the location falls within Greater Sage Grouse Priority Habitat Management Area.