

Interim Reclamation and Stormwater Inspection

April 15, 2024

Operator: FULCRUM ENERGY OPERATING LLC- #10805

Location ID: 463987

Inspection Document #: 697505289

Jackson County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PRU Alcorn 0880 S10 Pad
Location ID: 463987



Photo 1. 2023 NAIP illustrates the drilling completion operations have not been completed and interim reclamation has not been performed.

Inspection Photos
Location Name: PRU Alcorn 0880 S10 Pad
Location ID: 463987



Photo 2. Photo taken from the entrance of location. Photo illustrates the Location Operator sign.



Photo 3. Photo taken from the central location, facing East. Photo illustrates the drilling completion operations have not been completed and interim reclamation has not been performed.

Inspection Photos
Location Name: PRU Alcorn 0880 S10 Pad
Location ID: 463987




Photo 4. ECMC GIS aerial imagery illustrates the location falls within Greater Sage Grouse Priority Habitat Management Area.