



05.07.2024 09:48



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #116587 REM 28244 Photo #1. Area in foreground with pooled water and trash is Pit id 116589.**







05.07.2024 09:50



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #116587 REM 28244 Photo #4 inside Pit facility.







05.07.2024 09:50





05.07.2024 09:51





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #116587 REM 28244 Photo #9. Main pit, looking north.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #116587 REM 28244 Photo #10 looking north west



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #116587 REM 28244 Photo #11. looking north west.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #116587 REM 28244 Photo #12 main pit.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #116587 REM 28244 Photo #13. Former topsoil pile. Signs of recent activity with pile, appears dirt has been added and removed.**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #116587 REM 28244 Photo #14 Former topsoil pile. Signs of recent activity with pile, appears dirt has been added and removed.**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #116587 REM 28244 Photo #15 main pit. Appears that a sump has been built. Foreground of photo is the south west corner of pit. Note: hose coming out of pit.



Facility #116587 REM 28244 Photo #16. hoses going through fence on west side. Appears that fluid was being removed from this side of the pit. Note: gaps in fence (in orange circle)





**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #116587 REM 28244 Photo #17 Main pit looking to north east. Note: Hydrocarbon sheen on fluid surface.**



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Facility #116587 REM 28244 Photo #18 looking to south east. Note: Hydrocarbon sheen on fluid surface.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #116587 REM 28244 Photo #19 looking south across pit. Note: Oil and Hydrocarbon sheen on fluid surface.**







**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Facility #116587 REM 28244 Photo #21 outside of pit facility, fencing at left of photo is the northern perimeter of pit.**



