

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: ARISTOCRAT ANGUS-63N65W 4SWSW

Loc ID: 333169

Inspection: 714200948



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E

CA: Debris on various areas of location. See attached photos. Comply with Rule 606.

CA Resolution: Operator has reported that the location has been appropriately cleared of identified debris, trash and tumbleweeds to comply with Rule 606.



Exhibit A

CA: Capacity/contents are no longer legible on one tank. See attached photos. Comply with Rule 605.

CA Resolution: Operator has reported that capacity and content signage on identified tank has been updated to comply with Rule 605.