

Inspection Photos

May 8th, 2024

Operator: Beeman Oil and Gas INC - 7125

Location ID: 306888

Inspection Document #: 714000756

La Plata County, CO

Township: SWSE 12 33N 13W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Grommett 1
Location ID: 306888

5/8/24
+37.113415,-108.207455
328° NW



Photo 1. View of the center of the project area, well head marker and location sign.



Inspection Photos
Location Name: Grommett 1
Location ID: 306888



Inspection Photos
Location Name: Grommett 1
Location ID: 306888



Photo 3. Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west. Revegetation is progressing within the project area.

Inspection Photos
Location Name: Grommett 1
Location ID: 306888



Photo 4. View of the access road taken from the project area facing north.
Revegetation is progressing in this area.

Inspection Photos
Location Name: Grommett 1
Location ID: 306888



Photo 5. Large patches of field bindweed observed through the project area.

5/8/24
+37.113054,-108.207614
228° SW



Photo 6. Reference area comprised of sagebrush, juniper, indian rice grass and smooth brome.

