

Inspection Photos

May 8th, 2024

Operator: Williford Resources LLC - 96735

Location ID: 325229

Inspection Document #: 714000760

La Plata County, CO

Township: SWSW 13 33N 12W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Dye Hard 2
Location ID: 325229

5/8/24
+37.097591,-108.109554
32° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the project area taken from the southern edge facing north east.

API #: 067-05758

Inspection Photos
Location Name: Dye Hard 2
Location ID: 325229



Inspection Photos

Location Name: Dye Hard 2

Location ID: 325229



Inspection Photos
Location Name: Dye Hard 2
Location ID: 325229

5/8/24
+37.097839,-108.109564
178° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of project area on the left and reference area to the right.

API #: 067-05758

Inspection Photos
Location Name: Dye Hard 2
Location ID: 325229

5/8/24
+37.097377,-108.109569
100° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of the reference area comprised of smooth brome and crested wheatgrass.

API #: 067-05758