



OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

12308019

☐ NOTICE OF UNSATISFACTORY INSPECTION

☒ NOTICE OF SATISFACTORY INSPECTION

1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100

API No. 05- 123 - 8019		LEASE NAME: HUBERT #1	
LOCATION: SW SW 35 IN 67W		OPERATOR: AMOCO	
DATE: 1/11/96		INSPECTOR: SHELTON	
Insp. Type: PR	Insp. Status: PR	PA: Y N	Pass/Fail: (P) F Viol.: Y (N) NOV: Y N

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210)	OK	
Pits (Reserve/Production) (Rule 902, 903, 904)		
Fences (Rule 604.C.(3), 1003.A)		
Tank Battery Equipment (Rule 604)	To South 600'	
Fire Walls/Berms/Dikes (Rule 604)	OK	
General Housekeeping (Rule 603.G)	OK	
Spills (Oil/Water) (Rule 908)		
Bradenhead (Rule 207)		
Drilling Well/Workover (Rule 315)		
Surface Rehabilitation (Rule 317)		
Miscellaneous	PLUNGER LIFT	

CORRECTIVE ACTION REQUIRED:

Date Corrective Action Required By:

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

White



all Site

00036302