

**Inspection Photos**  
**Location Name: Bringelson 6-34-9-58 PAD**  
**Location ID: 434923**



**Photo 1 – Signs at Entrance**



**Photo 2 – Heater Treaters and ECD**

Inspection Photos  
Location Name: Bringelson 6-34-9-58 PAD  
Location ID: 434923



Photo 3 – Tank Battery



Photo 4 – Tank Battery Signs

**Inspection Photos**  
**Location Name: Bringelson 6-34-9-58 PAD**  
**Location ID: 434923**



**Photo 5 – Unused Water Tanks on Southside of Location**



**Photo 6 – Trash and Unused Equipment**

**Inspection Photos**  
**Location Name: Bringelson 6-34-9-58 PAD**  
**Location ID: 434923**



**Photo 7 – Unused Pipe Fittings**




**Photo 8 – Unused Electrical Wires and Equipment**

**Inspection Photos**  
**Location Name: Bringelson 6-34-9-58 PAD**  
**Location ID: 434923**



**Photo 9 – Wellheads**



**Photo 10 – Unused Building Equipment**

**Inspection Photos**  
**Location Name: Bringelson 6-34-9-58 PAD**  
**Location ID: 434923**



**Photo 11 – Unused Separator and Building Materials**



**Photo 12 – Unused Building Equipment**

**Inspection Photos**  
**Location Name: Bringelson 6-34-9-58 PAD**  
**Location ID: 434923**



**Photo 13 – Compressor**