

Inspection Photos

Location Name: GUNNISON ENERGY LLC, HOTCHKISS FEDERAL 12-89-612S89W/20SWNW

Location ID: 334446

Date: 5/13/2024



Location Entrance – Photo #01113




Southeast Corner of Location – Photo #01110

Inspection Photos

Location Name: GUNNISON ENERGY LLC, HOTCHKISS FEDERAL 12-89-612S89W/20SWNW

Location ID: 334446

Date: 5/13/2024



Wellhead – Photo #01114



Separator – Photo #01120

Inspection Photos

Location Name: GUNNISON ENERGY LLC, HOTCHKISS FEDERAL 12-89-612S89W/20SWNW

Location ID: 334446

Date: 5/13/2024



May 13, 2024 at 11:26:35



May 13, 2024 at 11:27:24

Tank Battery – Photo #01116

Stored Supplies/Equipment – Photo #01117

Inspection Photos

Location Name: GUNNISON ENERGY LLC, HOTCHKISS FEDERAL 12-89-612S89W/20SWNW

Location ID: 334446

Date: 5/13/2024



Unused Equipment – Photo #01119



Open-Ended Line – Photo #01122

Inspection Photos

Location Name: GUNNISON ENERGY LLC, HOTCHKISS FEDERAL 12-89-612S89W/20SWNW

Location ID: 334446

Date: 5/13/2024



Unsecured Separator – Photo #01123



Corroded Tank Wall/Chime – Photo #01118