

## Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-13 Pad

Location ID: 324475

Date: 5/13/2024



Location Entrance – Photo #01135



Wellhead – Photo #01138



## Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-13 Pad

Location ID: 324475

Date: 5/13/2024



Separator – Photo #01142



Tank Battery – Photo #01141

## Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-13 Pad

Location ID: 324475

Date: 5/13/2024



Stored Supplies – Photo #01147



Stored Supplies – Photo #01146



## Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-13 Pad

Location ID: 324475

Date: 5/13/2024



**Stored Supplies – Photo #01144**



**Unused Equipment – Photo #01150**



## Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-13 Pad

Location ID: 324475

Date: 5/13/2024



Open-Ended Line on Wellhead – Photo #01140



Bradenhead Not Accessible – Photo #01151



## Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-13 Pad

Location ID: 324475

Date: 5/13/2024



**Insufficient Erosion Control/BMP Needs Maintenance on  
Lease Road – Photo #01131**



**Insufficient Erosion Control/BMP Needs Maintenance on  
Lease Road – Photo #01132**