

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 5/13/2024



Location Entrance – Photo #01154



Wellhead – Photo #01156

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 5/13/2024



May 13, 2024 at 12:48:55

Wellhead – Photo #01158



May 13, 2024 at 12:53:32

Separator/Meter – Photo #01161

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 5/13/2024



Separator – Photo #01167



Tank Battery – Photo #01163

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 5/13/2024



Stored Supplies – Photo #01159



Stored Supplies – Photo #01164

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 5/13/2024



Debris – Photo #01166



Debris – Photo #01168

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 5/13/2024



Debris – Photo #01169



Unsecured Pump House – Photo #01165

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 5/13/2024



Open-Ended Line – Photo #01170



Open-Ended Line – Photo #01171

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 5/13/2024



Open-Ended Line – Photo #01172



Open-Ended Line – Photo #01173

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 5/13/2024



Open-Ended Vent – Photo #01179



**Insufficient Erosion Controls/BMP Needs Maintenance on
Lease Road – Photo #01131**

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/18-43 Pad

Location ID: 324485

Date: 5/13/2024



**Insufficient Erosion Controls/BMP Needs Maintenance on
Lease Road – Photo #01132**

– Photo #0