

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



Photo # 7325 From entrance to location

Photo # 7326 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



May 16, 2024 at 11:41:01 AM
CO



May 16, 2024 at 12:00:23 PM
CO

Photo # 7327 Location

Photo # 7328 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



Photo # 7329 Location



Photo # 7330 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



Photo # 7331 Staining in secondary containment




Photo # 7332 Wellhead sign weathered & becoming illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC SILT VALLEY 34C-22-692 Pad

Location ID: 335438



Photo # 9283 From inspection 708903254 conducted on 03/11/2024 - Unused equipment/ECD disconnected

Photo # 7333 Unused equipment/ECD disconnected