

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



Conflicting and incorrect information tank battery signs

Conflicting and incorrect information tank battery signs

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



As signs are replaced additional information is required

As signs are replaced additional information is required

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



Unused equipment



Unused equipment

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



Chemical and tank pad from Northwest corner



Well pad location from Northeast corner

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



May 20, 2024 at 11:51:09 AM

Chemical and tank battery from Southwest corner



May 20, 2024 at 11:55:39 AM

Well pad location from Southeast corner

Caerus Piceance LLC
Piceance Creek Unit-62S97W 11NESW
Location ID: 335712



Well pad location from Southwest corner



Separator and manifold pad from Southeast corner