

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-11 Pad

Location ID: 412922

Date: 5/13/2024



Location Entrance – Photo #01183



Northeast Corner of Location – Photo #01185

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-11 Pad

Location ID: 412922

Date: 5/13/2024



May 13, 2024 at 13:22:01

Wellhead – Photo #01187



May 13, 2024 at 13:28:30

Separators – Photo #01196

Inspection Photos


Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-11 Pad

Location ID: 412922

Date: 5/13/2024



Tank Battery – Photo #01191



Trash/Debris – Photo #01192



Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-11 Pad

Location ID: 412922

Date: 5/13/2024



Trash/Debris – Photo #01193



Trash/Debris – Photo #01194

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-11 Pad

Location ID: 412922

Date: 5/13/2024



Stored Supplies – Photo #01189



Stored Supplies – Photo #01190

Inspection Photos

Location Name: GUNNISON ENERGY LLC, DGU Federal 1289/17-11 Pad

Location ID: 412922

Date: 5/13/2024



**Insufficient Erosion Control/BMPs Need Maintenance on
Lease Road – Photo #01131**



**Insufficient Erosion Control/BMPs Need Maintenance on
Lease Road – Photo #01132**