

Inspection Photos

Location Name: SG INTERESTS I LTD, HENDERSON-611S90W/9SWNE

Location ID: 324477

Date: 5/13/2024



Location Entrance – Photo #01200



East End of Location – Photo #01201

Inspection Photos

Location Name: SG INTERESTS I LTD, HENDERSON-611S90W/9SWNE

Location ID: 324477

Date: 5/13/2024



Wellhead – Photo #01203



Tank Battery – Photo #01205

Inspection Photos

Location Name: SG INTERESTS I LTD, HENDERSON-611S90W/9SWNE

Location ID: 324477

Date: 5/13/2024



Gas Meter – Photo #01211



Pump House Roof Damage – Photo #01208

Inspection Photos

Location Name: SG INTERESTS I LTD, HENDERSON-611S90W/9SWNE

Location ID: 324477

Date: 5/13/2024



Pump House Roof Damage – Photo #01213



Wildlife Entry Hazard at Load Line Housing – Photo #01214