

Inspection Photos

Location Name: CAERUS PICEANCE LLC, WALLING-68S96W/1NWSE

Location ID: 334062

Date: 5/14/2024



May 14, 2024 at 11:17:49
Parachute CO 81635
United States

Location Entrance – Photo #01219



May 14, 2024 at 11:24:51
Parachute CO 81635
United States

Wellheads – Photo #01224

Inspection Photos

Location Name: CAERUS PICEANCE LLC, WALLING-68S96W/1NWSE


Location ID: 334062

Date: 5/14/2024



May 14, 2024 at 11:21:25
Parachute CO 81635
United States

Separators – Photo #01221



May 14, 2024 at 11:18:41
Parachute CO 81635
United States

Tank Battery – Photo #01220

Inspection Photos

Location Name: CAERUS PICEANCE LLC, WALLING-68S96W/1NWSE

Location ID: 334062

Date: 5/14/2024



**Lack of Stabilization/Insufficient Vehicle Tracking BMPs at
Location Entrance/Exit – Photo #01225**