

Inspection Photos

05/06/2024

Operator: GUNNISON ENERGY LLC #10515

Location ID: 324485

Inspection Doc: 696205822

Gunnison County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 324485



Photo 1: Photos 1-2 taken from the north end of the working pad surface. Photos provide an overview of the Location from east, southeast, southwest and west. Photos also show interim reclamation to reduce the Location to areas only needed for production has not been performed in accordance with 1003 Rules.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 324485



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 324485



Photo 3: Photo taken from the Topsoil stockpile on the northwest end of the Location. BMPs to stabilize soils are missing or insufficient; soils are bare and at risk to wind and water erosion.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: GUNNISON ENERGY LLC #10515

Location ID: 324485



Photo 4: Image from doc. 696205083. Photo a Google Earth aerial image of the Location. Photo shows well coordinates from the Scout Cards; as drilled coordinates for Well API 051-06075 incorrect; coordinates for the abandoned Well API 051-06122 also incorrect.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources