

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11SESE

Location ID: 334727

Date: 5/16/2024



Location Entrance – Photo #01237



Southern End of Location – Photo #01238

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11SESE

Location ID: 334727

Date: 5/16/2024



Wellheads – Photo #01239



Separators – Photo #01241

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11SESE

Location ID: 334727

Date: 5/16/2024



Tank Battery – Photo #01240



Open-Ended Load Line – Photo #01242

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11SESE

Location ID: 334727

Date: 5/16/2024



Open-Ended Load Line – Photo #01243



Open-Ended Line – Photo #01244

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11SESE

Location ID: 334727

Date: 5/16/2024



Open-Ended Line – Photo #01247



Stored Supplies – Photo #01245