

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, C&C Energy GM/313-12 Frac Pad

Location ID: 334646

Date: 5/16/2024



Location Entrance – Photo #01262



Separators – Photo #01268



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, C&C Energy GM/313-12 Frac Pad

Location ID: 334646

Date: 5/16/2024



**Tank Battery – Photo #01270**



**Uncovered Wellhead Cellar – Photo #01264**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, C&C Energy GM/313-12 Frac Pad

Location ID: 334646

Date: 5/16/2024



Uncovered Wellhead Cellars – Photo #01266



Stored Equipment – Photo #01277



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, C&C Energy GM/313-12 Frac Pad

Location ID: 334646

Date: 5/16/2024



Open-Ended Line – Photo #01275



Open-Ended Line – Photo #01271

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, C&C Energy GM/313-12 Frac Pad

Location ID: 334646

Date: 5/16/2024



**Wildlife Entry Hazard – Photo #01273**