

Inspection Photos  
Location Name: Elkhorn Company B9  
Location ID: 318601




Photo 1 Location.



Photo 2 WH.

Inspection Photos  
Location Name: Elkhorn Company B9  
Location ID: 318601



Photo 3 WH sign is faded not legible.

Photo 4 Ancillary equipment.