

Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Location Name: ARISTOCRAT ANGUS 63N65W 4SESW MULTI WELL PAD

Loc ID: 332754

Inspection: 714200947



Exhibit A



Exhibit B

CA: It appears contents/capacity is no longer legible on two tanks. See attached photos. Comply with Rule 605.h.

CA Resolution: Operator has reported that capacity and content signage has been updated on the identified tanks to comply with Rule 605.h.



Exhibit A

CA: One wellhead has incorrect signage. See attached photo. Comply with Rule 605.d.

CA Resolution: Operator has updated sign with WH label, while waiting for permanent sign to comply with Rule 605.d.



Exhibit A



Exhibit B

CA: Debris on various areas on location. See attached photos. Comply with Rule 606.

CA Resolution: Operator has reported that the location has been appropriately cleared of identified debris, trash and tumbleweeds to comply with Rule 606.