

Inspection Photos

API: 043-06157

Operator: **INCREMENTAL OIL & GAS (FLORENCE) LLC**

Inspection Date: 5/20/2024

County: FREMONT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west at the location. All unused areas of the location must be reclaimed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:334402 | Date: 5/20/2024

Inspection Photos



Photo 2. Facing back south at the location. The wellhead has been covered with material.



Inspection Photos



Photo 3. Facing east at the northwest side of the location. The pipe risers and utility appear to have been removed. All unused areas of the location must be reclaimed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:334402 | Date: 5/20/2024