



99999999

OIL & GAS CONSERVATION COMMISSION  
FIELD INSPECTION REPORT

12308714

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input checked="" type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- 123 - 08714		LEASE NAME: Zarlenzo 3-32-2	
LOCATION: SUNE-S29-IN-67W		OPERATOR: Union Pac. Rues	
DATE: 6/3/1997		INSPECTOR: Pavelka	
Insp. Type: SR	Insp. Status: PA	PA: Y I N	Pass/Fail: P F Viol.: Y N NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)		
<b>Miscellaneous</b>		

**CORRECTIVE ACTION REQUIRED:** Meter gone - location  
graded - Looks good

Date Corrective Action Required By: \_\_\_\_\_ Date Remedied: \_\_\_\_\_

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



50000121

White - File Canary - Operator Pink - Well Site