

COLORADO OIL & GAS CONSERVATION COMMISSION

FIELD INSPECTION REPORT

(C)

<input type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- <u>123 - 07972</u>		LEASE NAME: <u>Zarlengo 1-42-2</u>	
LOCATION: <u>SENE-S29-N-67W</u>		OPERATOR: <u>UPRE</u>	
DATE: <u>3/18/96</u>		INSPECTOR: <u>Ravelka</u>	
Insp. Type: <u>SR</u>	Insp. Status: <u>PA</u>	PA: <u>(I)</u> N	Pass/Fail: P <u>(F)</u> Vol.: Y N NOV: Y N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))		
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous	<u>road & location</u> <u>meat capped & repaired</u>	

CORRECTIVE ACTION REQUIRED: <u>meter run still on location</u>	
Date Corrective Action Required By:	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



White - File Canary - Operator Pink - Well Site