

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Energy & Carbon Management Commission
40.16372, -104.7012, 1485.7m, 45°
May 22, 2024 09:49:56



Energy & Carbon Management Commission
40.16381, -104.70129, 1485.1m, 46°
May 22, 2024 09:50:49

Photo 1: Tank Battery Signs

Photo 2: Debris



Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 3: Debris



Photo 4: Debris

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 5: Debris



Photo 6: Debris

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 7: Debris



Photo 8: Debris removed

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 9: Debris




Photo 10: Debris

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537




Photo 11: Debris



Photo 12: Debris removed

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 13: Debris



Photo 14: Weeds removed

Inspection Photos
Location Name: Nichols 10-6
Location ID: 329537



Photo 15: weeds removed



Photo 16: Weeds removed