

# Inspection Photos

API: 071-08739

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 5/24/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southwest along the access road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 2.** Facing east toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API:071-08739 | Date: 5/24/2024



## Inspection Photos



**Photo 3.** Facing toward the pw pit.

