

Inspection Photos

May 21st 2024

Operator: BP American Production Company -
10000

Location ID: 413525

Inspection Document #: 714000770

La Plata County, CO

Township: NWSW 21 35N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lewis 2
Location ID: 413525

5/21/24
+37.286404,-107.647005
144° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 1. View of the project area taken from the western edge facing south east.

API #: 067-09747

Inspection Photos
Location Name: Lewis 2
Location ID: 413525



Photo 2. Cardinal photos taken from the center of the project area. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Lewis 2
Location ID: 413525



Photo 3. Cardinal photos taken from the center of the project area. Left photo facing south, right photo facing west.

Inspection Photos
Location Name: Lewis 2
Location ID: 413525



Photo 4. View of musk thistle stalks from last season and new musk thistle establishment observed in southern portion of the disturbance, over 200 individuals observed.

Inspection Photos
Location Name: Lewis 2
Location ID: 413525



Photo 5. View of mullein stalks from last season and new mullein establishment observed in southern and western portions of the disturbance, over 500 individuals observed.

Inspection Photos
Location Name: Lewis 2
Location ID: 413525



Photo 6. View of bare soils in the northeastern portion of the disturbance. Area needs additional reclamation.