

Inspection Photos

May 21st 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 385841

Inspection Document #: 714000774

La Plata County, CO

Township: SWNE 34 35N 8W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Huber Thorn 1-34
Location ID: 385841



Photo 1. View of the project area taken from the northern edge facing center.



Inspection Photos
Location Name: Huber Thorn 1-34
Location ID: 385841



Photo 2. Cardinal photos taken from the center of the disturbance. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Huber Thorn 1-34
Location ID: 385841



Photo 3. Cardinal photos taken from the center of the disturbance. Left photo facing south, right photo facing west. Note: prairie dog colony appears to be affecting establishment of perennial vegetation within the central portion of project area.

Inspection Photos
Location Name: Huber Thorn 1-34
Location ID: 385841



Photo 4. View of the access road taken from the center of the project area facing northwest.

Inspection Photos
Location Name: Huber Thorn 1-34
Location ID: 385841



Photo 5. Reference area comprised predominantly of smooth brome.

