

Inspection Photos

API: 071-09287

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/28/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest at the beginning of the access road that remains by approved variance.



Inspection Photos



Photo 2. Facing southwest. There is an erosion along this area which should be repaired with BMP's



Inspection Photos



Photo 3. Facing southwest along the access road. There is a Russian olive tree shown at red arrow that is considered a noxious weed and needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09287 | Date: 5/28/2024

Inspection Photos



Photo 4. Facing west toward the location..



Inspection Photos



Photo 5. The vegetation is not establishing at the center of the location.



Inspection Photos



Photo 6. West side of the location facing east. The vegetation is not establishing at the center of the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09287 | Date: 5/28/2024

Inspection Photos



Photo 7. Facing east at the south fill slope which is stabilized with vegetation.

